

ITEM NO: 1316K-1 EK Headboard & Posts & Short Canopy

BOX: 1316K-1

1316K-2 EK Footboard & Posts & Short Canopy & Slat Roll

1316-3 QN/EK Side Rails & Long Canopy

Thank you for purchasing this quality product. Be sure to check all packing material carefully for small parts that may have come loose inside the carton during shipment.



For items use on wooden floor, hard surfaces or carpets, it is recommended to install protective pads under all legs and supports to avoid/prevent from damages/scratches and discoloration.

TOOLS REQUIRED (NOT PROVIDED)
PHILLIPS SCREWDRIVER

A

Hardware may loosen over time, periodically check to make sure all connection are tight. Re-tighten if necessary.

HEADBOARI				
LIST OF HARDWARE				
No.		Description		Q'ty
A	O mminimin	Allen Bolt	Ø1/4" - 20x2-3/8"	8 Pcs
В	0	Spring Washer	Ø1/4"	8 Pcs
С	0	Flat Washer	Ø1/4" x 3/4"	8 Pcs
D		Allen Key	M4	1 Pc
				•

	LIST OF PARTS			
No.	Description	Picture	Q'ty	
1	Headboard		1 Pc	
2	Headboard Cap Canopy(Left & Right)		2 Pcs	
3	Headboard Cap (Left & Right)		2 Pcs	
4	Short Canopy Headboard	-	1 Pc	

FOOTBOARD BOX: 1316K-2

LIST OF HARDWARE				
No.	Description			Q'ty
A	O 111111111111111111111111111111111111	Allen Bolt	Ø1/4" - 20x2-3/8"	8 Pcs
В	0	Spring Washer	Ø1/4"	8 Pcs
С	0	Flat Washer	Ø1/4" x 3/4"	8 Pcs
D		Allen Key	M4	1 Pc
Е	®	Screw	M4 x 1-1/4"	30 Pcs

LIST OF PARTS			
No.	Description	Picture	
5	Footboard		1 Pc
6	Footboard Cap Canopy(Left & Right)	=	2 Pcs
7	Footboard Cap (Left & Right)	60	2 Pcs
8	Short Canopy Footboard		1 Pc
9	Slats		14Pcs/ Set
10	Slat Support Leg		3 Pcs

SIDE RAIL BOX: 1316-3

LIST OF HARDWARE				
No.	Description			Q'ty
A	O mminimini	Allen Bolt	Ø1/4" - 20x2-3/8"	4 Pcs
В	0	Spring Washer	Ø1/4"	4 Pcs
С	0	Flat Washer	Ø1/4" x 3/4"	4 Pcs
D		Allen Key	M4	1 Pc
F		Hanger Bolt	Ø5/16" -18x3-1/2"	8 Pcs
G		Hexagon Nut	Ø5/16"	8 Pcs
Н		Spring washer	Ø5/16"	8 Pcs
I	0	Flat washer	Ø5/16" x 1/2"	8 Pcs
K	CS	Wrench	1/2"	1 Pc

 11.1010					
	LIST OF PAR	ats			
No.	Description	Picture	Q'ty		
11	Side Rail	<u> </u>	2 Pcs		
12	Long Canopy Bed Side Rail		2 Pcs		
13	Center Slat Support		1 Pc		

Page 1 of 4 MADE IN VIET NAM



ITEM NO: 1316K-1 EK Headboard & Posts & Short Canopy

1316K-2 EK Footboard & Posts & Short Canopy & Slat Roll

1316-3 QN/EK Side Rails & Long Canopy


Thank you for purchasing this quality product. Be sure to check all packing material carefully for small parts that may have come loose inside the carton during shipment.



For items use on wooden floor, hard surfaces or carpets, it is recommended to install protective pads under all legs and supports to avoid/ prevent from damages/ scratches and discoloration.



Hardware may loosen over time, periodically check to make sure all connection are tight. Re-tighten if necessary.



Page 2 of 4

MADE IN VIET NAM



ITEM NO: 1316K-1 EK Headboard & Posts & Short Canopy

1316K-2 EK Footboard & Posts & Short Canopy & Slat Roll

1316-3 QN/EK Side Rails & Long Canopy

Thank you for purchasing this quality product. Be sure to check all packing material carefully for small parts that may have come loose inside the carton during shipment.




For items use on wooden floor, hard surfaces or carpets, it is recommended to install protective pads under all legs and supports to avoid/ prevent from damages/ scratches and discoloration.



Hardware may loosen over time, periodically check to make sure all connection are tight. Re-tighten if necessary.

OPTION - 1: Assembly King Bed with Cap at top



Page 3 of 4



ITEM NO: 1316K-1 EK Headboard & Posts & Short Canopy

1316K-2 EK Footboard & Posts & Short Canopy & Slat Roll

1316-3 QN/EK Side Rails & Long Canopy

Thank you for purchasing this quality product. Be sure to check all packing material carefully for small parts that may have come loose inside the carton during shipment.



For items use on wooden floor, hard surfaces or carpets, it is recommended to install protective pads under all legs and supports to avoid/ prevent from damages/ scratches and discoloration.



Hardware may loosen over time, periodically check to make sure all connection are tight. Re-tighten if necessary.

OPTION - 2: Assembly King Bed with Cap Canopy at top

